



10/612,831 PATENT

CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,395,532
Issue Date : July 1, 2008
Inventor : Antonio Maria Borneo et al.

Docket No. : 851763.435
Date : September 3, 2008

Certificate

Mail Stop Certificate of Correction
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

SEP 09 2008
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents:

A certificate of correction is respectfully requested in the above-identified patent.
The following errors have been made:

In column 14, claim 17, line 19, the section "processor to said instruction set stream" is erroneous and instead should read as -- processor to an instruction set stream --.

In Column 14, claim 20, line 42, the section "load measurement comprises number of operations" is erroneous and instead should read as -- load measurement comprises a number of operations --.


The errors are of a clerical nature, are of minor character, would not constitute new matter or require reexamination, and were made in good faith.

RECEIVED- JETCO
Patent Publication

SEP - 9 2008

Attached is the certificate of correction, which indicates the corrections to be made, by reference to the category and page number in the printed patent. The Director is hereby authorized to charge payment of any fees associated with this communication only to Deposit Account No. 19-1090.

Respectfully submitted,
SEED Intellectual Property Law Group PLLC



Timothy L. Boller
Registration No. 47,435

TLB:at

Enclosures:

Certificate of Correction
Postcard

SEED Intellectual Property Law Group PLLC
701 Fifth Avenue, Suite 5400
Seattle, Washington 98104-7092
Phone: (206) 622-4900
Fax: (206) 682-6031
1219788_1.DOC

RECEIVED - 10/2/2008
U.S. Patent and Trademark Office
SEP - 9 2008

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,395,532 B2
DATED : July 1, 2008
INVENTOR : Antonio Maria Borneo et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 14

Line 19, "processor to said instruction set stream" should read as -- processor to an instruction set stream --

Line 42, "load measurement comprises number of operations" should read as -- load measurement comprises a number of operations --

RECEIVED
U.S. PATENT AND TRADEMARK OFFICE
SEP 10 2008

MAILING ADDRESS OF SENDER:

Timothy L. Boller
Seed Intellectual Property Law Group PLLC
701 Fifth Avenue, Suite 5400
Seattle, Washington 98104

PATENT NO. 7,395,532 B2

SEP - 9 2008

No. of additional copies

0

Burden hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.